

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




Fig. 1




Fig. 2




Fig. 3




Fig. 4

The diagram shows a table with three rows and 13 columns. The first row is labeled 'CALIBRATION VALUE' (172) and contains values 10, 12, 14, 16, 18, 20, 22, 24, 26, 28. The second row is labeled '# OF ALTERED ELEMENTS' (180) and contains values 0, 1, 2, 3, 4, 5, 6, 7, 8, 9. The third row is labeled 'IMPEDANCE VALUE' (190) and contains values A, B, C, D, E, F, G, H, I, J. A bracket (182) groups the first two columns (10, 0, A) and is labeled 174. A bracket (192) groups the last two columns (28, J). An arrow (170) points to the column containing the value 18.

CALIBRATION VALUE	10	12	14	16	18	20	22	24	26	28
# OF ALTERED ELEMENTS	0	1	2	3	4	5	6	7	8	9
IMPEDANCE VALUE	A	B	C	D	E	F	G	H	I	J

Fig. 5




Fig. 7




Fig. 6




Fig. 8